

Name of work : Repairs to recoil unit & idler group (L.H Side) of JCB JS 80 No 109485

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
	Repairs to recoil unit of JCB JS 80 No. 109482 by removing the track chain assly from machine, checking and removing wornout parts, providing & fitting new spares as per OEM specification				
A	Cost of Spare Parts				
1	331/20045 - Yoke	1	No		
2	331/20048 - Bracket	2	No		
3	998/10443 - Kit Seal	1	No		
4	904/20188 - Seal	1	No		
5	904/20190 - Seal/Wiper Seal	1	No		
6	904/20189 - Seal	2	No		
7	826/10579 - Pin Tention	2	No		
8	25/964902 - Solenoid Coil	1	No		
	Total A				
B	Cost of Labour Charges				
1	Dismantling Track chain by removing master pin/No. (UC/01)	1	Job		
2	Reassembling of track chain & fitting of master pin by hydraulic press after repair (UC/15)	1	Job		
	Total B				
	Total A + B				
	SGST 9%				
	CGST 9%				
	Grand Total				
	Say Amount				



Deputy Engineer
Mechanical Subdivision No.2
Osmanabad