Work Details

Name of work : Providing & fitting Fan Belt & Water Pump to TATA Hitachi Zx 120 No. 52475.

Sr. No.	Part Details		Qty / Unit		Rate	Total
	Part Number	Description				
	Providing & fitting following spares as per OEM specification & part no given below to TATA Hitachi Zx120 No 52475.					ज्ञ
A	Cost of Spares	मा.सं.वेषिवज्यांशन् // १४४/२०२३ हि. १४४/२०२३ : . हे	ान दिल्	ল্যান জিলান্ট ম	ाल विभावजी	
1	4440813	Fan Belt	1	No	to califate mailer	
2	897253-0281	Water Pump Assly	1	No		र हिरासल्यान
			(Cost of	Spares Rs :	किन्छ व विवय
В	Labour Chagges					9 s
1	Radiator Chock up removing by cleaning all tubes soldering the tubes with top and bottom removing and refitting.1Job				ष कठन तिन्तक १०० चा लिपलपे एपलियात दरस्वी	
	Cost of Labour Rs :					9
1 11000	Cost of Spares+Labour Rs :					2 X. 400
	GST @ 18% Rs :					
	Grand Total Rs					18

(S.S.Garad) Deputy Engineer Mechanical Sub division No. 3, Osmanabad

影