

## WORK DETAILS

**Name of work : Repair & reconditioning of L.H.Side Track Chain Assembly of JCB JS 140 Hyd. Excavator No. 2439384.**

Excavator No. 2439384

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & reconditong of L.H.Side Track Chain Assembly of JCB JS 140 Hyd. Excavator No. 2439384 by Removing Track Chain Assly from machine ,dismantaling , Removing damaged link ,bush, pin and removing grouser shoe bolts by gas cutting & refitting of track chain with new parts as per OEM specifications etc complete.					
A	Cost of Sapare charges					
1	331 / 17177	TRACK LINK L.H	5	No.		
2	331 / 17176	TRACK LINK R.H	5	No.		
3	331 / 17179	TRACK PIN REGULAR	5	No.		
4	331 / 21733	TRACK BUSHING REGULAR	5	No.		
5	331 / 21731	DUST SEAL	10	No.		
6	331 / 17162	TRACK PIN MASTER	1	No.		
7	331 / 17161	TRACK BUSHING MASTER	1	No.		
8	JNA 0082	TRACK SHOE	4	No.		
9	JNA 0085	TRACK BOLT	24	No.		
B	LABOUR CHARGES					
1	Dismantling Track chain by removing master pin/No		1	Job		
2	Removing & refitting new link bush, pin of track chain/Set (inner & outer)		5	Job		
3	Removing grouser shoe bolts by gas cutting & refitting of grouser shoe with new shoe bolts / Shoe		4	Job		
4	Reassembling of track chain & fitting of master pin by hydraulic press		1	Job		
					GST 18%	
					Total Rs	

  
Deputy Engineer

Mechanical Subdivision, Latur