

ENQUIRY

Name of Work : **Repair & reconditioning of L.H. Side Boom Cylinder Assembly
of JCB JS 140 Excavator No. 243981**

Sr. No .	Description	Qty	Estimated Rates		Remark
			Rate	Amount	
1	2	3	4	5	6
	Repair & reconditioning of L.H. Side Boom Cylinder Assembly of JCB JS 140 Excavator No. 243981 by Removing L.H.Side Boom Cylinder Assly from machine ,dismantaling eye end rebuilding to std size & Replacing seal kit , bushing with new parts as per OEM specifications etc complete.				
A	Cost of Spares Charges				
1	335 / B 6905 SEAL KIT	1 No.			
2	550 / 43349 H.E.BUSHING	1 No.			
3	550 / 43351 BUSH	1 No.			
4	550 / 43353 BUSH	1 No.			
5	550 / 43336 BIMETAL BUSH	1 No.			
6	550 / 43341 SNAP RING	1 No.			
7	550 / 30108 SNAP RING	1 No.			
8	627/10352 HOSE BOOM	1 No.			
9	333/Y5744 HOSE 12 BSPUHP	1 No.			
B	Cost of Labour Charges				
1	Removing L.H.Side Boom Cylinder Assly from machine	1 Job			
2	Dismantling the cylinder assly , cleaning , replacing seal service kit with test & trial	1 Job			
3	Eye end re-building & machining to std size	2 Job			
4	Cylinder Barrel End bushing replacement	2 Job			
5	Removing & refitting Non hidden high pressure hoses	2 Job			
	Total Rs.				
	Add GST				
	Grand Total Rs.				



Deputy Engineer
Mech. Sub Division (L.T.P) Latur