

Name of work :Repairs and Reconditining to boom jack assly & Hydraulic System of JCB JS-80
No.109482

Sr. No.	Description	Qty	Unlt	Rate	Amount
1	2	4	5	6	7
A	Repairs and Reconditining to boom jack assly & Hydraulic System of JCB JS-80 No.109482 by Providing and fitting Hydraulic Hoses as per OEM Specification and part no given below				
1	550/41174 - Boom Seal kit	1	No		
2	229/00424 - Hose	2	No		
3	333/PO731 - Bucket & Arm Hose	2	No		
4	333/PO724 - Bucket & Arm Hose	2	No		
5	25/964902 - Hose	1	No		
B	Cost of Labour Charges				
1	Removing Boom jack assly from machine & refitting after repaire (H/08)	1	Job		
2	Dismantling of Jack assly,cleaning,inspection & resplacement of seal with test and trial (H/09)	1	Job		
3	For Removing and Refitting above Hydraulic Hoses (H/06)	7	Job		
4	Fuel tank opning,cleaning,brazing & refitting (E/43)	1	Job		
Total :					
GST 9 %					
GST 9 %					
Grand total					
Say Amount					


 Deputy Engineer
 Mechanical Subdivision No.2
 Dharashiv