



Measurement sheet

Name of Work : Repairs to swing bearing of TATA Hitachi Zaxis 120H Excavator
Sr. no. 52475 by way of replacing following spares as per O.E.M. Specification and part nos. with cost of material and labour charges etc. complete job.

Sr.No.	Description	Qty.	Rate	Amount
1	Swing bearing i.e. round table, bolts, balls and seal replacing A/13/26	1	3174	3174
2	Replacing following damages spares with part no given below and as per OEM specification.			
2.1	4425980 Pin knock	1	✓ 116	✓ 116
2.2	J931695 Bolt	36	✓ 165	✓ 5940
2.3	4272297 packing	1	✓ 50	✓ 50
2.4	4483676 seal	1	✓ 4824	✓ 4824
2.5	4127708 Support	60	✓ 1088	✓ 65280
2.6	4289757 Seal (new part no 4634010)	1	✓ 8802	✓ 8802
2.7	4315493 seal (New part no 4634010)	1	✓ 8802	✓ 8802
2.8	4428919 ball	99	✓ 535	✓ 52965
			Total =	146779
			G.S.T.18%	26420.22
			Total =	173199.22
			Say=	173199

(In Words:- Rs. One lakh seventy ^{five} three thousand ^{nine} one hundred ^{forty five} ninety nine only).


Shri. B.V. Satpute,
Sect. Engr.


(Shri. C.T. Satpute)
Deputy Engineer,
Mechanical Sub Division No.3
Osmanabad

ABSTRACT

Name of Work: Repairs to swing bearing of TATA Hitachi Zaxis 120H Excavator Sr. no. 52475 by way of replacing following spares as per O.E.M. Specification and part nos. with cost of material and labour charges etc. complete job.


Sr.No.	Description	Qty.	Rate	Amount
1	Repairs to swing bearing of TATA Hitachi Zaxis 120H Excavator Sr. no. 52475 by way of replacing following spares as per O.E.M. Specification and part nos. with cost of material and labour charges etc. complete job.			
	Cost of spare parts	1	133969	143605
	Cost of labour	1	3174	3174
			Total =	146779.00
			G.S.T. 18% =	26420.22
			Total	173199.22
			Say =	173199.00


(In Words:- Rs. . One lakh seventy three thousand one hundred ninety nine only). 1,76,945/-

CERTIFICATE

Certified that,

- 1- Repairs are essential to keep machine in good working condition.
- 2- Spares are not available in dept. stores.
- 3- Such type of repair jobs are not carried out in our work shop due to lac of facilities.
- 4- Rates are reasonable.
- 5- Certify that the above repairs work is to be carried out immediately as the Dozer is urgently required on Project Canal Earth Work.


Shri. B.V. Satpute,
Sect. Engr.


(Shri. C.T. Satpute)
Deputy Engineer,
Mechanical Sub Division No.3
Osmanabad

sanctioned Estimate No.....the year. 2020-21
Estimate technically Sanctioned for Rs. ~~173199~~ 1,46,945/-
Rs. In Word.. ~~One Lakh.. Seventy Three Thousand One Hundred~~
~~Nine~~ One lakh seventy six thousand nine hundred and forty
five only.


Executive Engineer
Mechanical Division
Osmanabad