


Name of Work : Repairs to Fuel line assembly armature rewinding, Wheel greassing etc. of Tata Tipper MH 20 CU 201

Sr.No	Description of Job	Qty.
A	General Repair of Tata Tipper No. MH 20 CU 201 with cost of Labour charges as below :	
1	Complete fuel line opening, cleaning, checking, brazing and refitting	1 Job
2	Fuel tank opening, cleaning, brazing and refitting.	1 Job
3	Radiator chockup removing by cleaning all the tubes, soldering the tubes with top and bottom removing and refitting	1 Job
4	Silence/muffler repairing by removing, cleaning and refitting with welding work	1 Job
5	Starter Armature Rewinding with material	1 Job
6	Steering unit overhauling	1 Job
7	Front wheel greassing including oil seal changing/NO.	2 Job
8	Rear wheel hub greassing including oil seal changing/No.	2 Job
9	King pin overhauling and refitting	1 Job
10	Four spring leaf assembly, removing, dismantling, recambering and refitting assembly.	1 Job
11	Front mudguard damaged and rusted inner and outer wheel house new pieces welding, patching and finishing.	2 Job
12	Rear mudguard damaged and rusted inner and outer wheel house new pieces welding, patching and finishing.	2 Job
13	Front bumper removing repairing by welding, straightening, denting and refitting.	1 Job
14	Door locks removing repairing and refitting Door adjusting and setting/No.	2 Job
15	Branding on vehicle and front and rear number plate, flooring pieces patching and welding.	1 Job
16	Complete flooring rusted portion cutting and new flooring pieces patching and welding.	1 Job
17	Complete seat and back rest cushioning with coir foam 4" with u foam 2" with best quality rexine cover	1 Job


Deputy Engineer,
Mechanical subdivision no. 2,
Osmanabad.