

Abstract


Repairs to JCB JS 81 Sr, No. 2426856

No	Part NO.	Description	Qty	Rate	Amt
A	Repairs to track motor group LH of JCB JS 81 Sr. No. 2426856 by replacing following spares. Charges includes cost of material, labour charges and all taxes.		1 Job	49253	49253
1	332/Y6717	Floating seal kit	1	32807.63	32807.63
2	332/Y6727	Thrust washer 1	1	2244.07	2244.07
4	332/Y6733	Needle roller bearing	2	993.22	1986.44
				Sub Total A	37038.14
				Add GST @ 9%	3333.43
				Add GST @ 9%	3333.43
				Total A	43705.00
B		Labour charges			
1	A/11	Overhauling of track motors by dismantling, cleaning and inspection of parts.	1	2351	2351
2	A/10	Removing & refitting of track motor	1	2351	2351
				Sub Total B	4702
				Add SGST @ 9%	423.18
				Add CGST @ 9%	423.18
				Total B	5548.36
				Grand Total	49253


CERTIFICATE

- 1 The Spares are not available in dept. stores .
- 2 The rates are as per market rates & reasonable .
- 3 Due to lack of facility in dept. work shop & urgency of work ,The job work is proposed for outside agency.

Prepared by


Sectional Engineer
Regional Workshop Sub Division,
Nashik

Checked By.



Deputy Engineer
Regional Workshop Sub Division
Peth Road, Nashik-4


R. No. /

ITS -1 of 2020-21

Technically sanctioned for Rs. 49253/-

Rs. Forty Nine thousand Two Hundred Fifty Three only;


Executive Engineer


Mechanical Division
NASHIK - 4.

2021-2-18 14:01

Scanned with CamScanner