ENQUIRY

Name of Work: Repair & reconditiong of Arm Cylinderr Assembly of Tata Hitachi Zaxis 120 Excavator No. 51573

Sr.	Description		Estimated Rates		Damada
No ·	Description	Qty	Rate	Amount	Remark
1	2	3	4	5	6
	Repair & reconditiong of Arm Cylinder Assembly of Tata Hitachi Zaxis 120 Excavator No. 51573 by Removing Arm Cylinder Assly from machine ,dismantaling eye end rebuilding to std size & Replacing seal kit , bushing with new parts as per OEM specifications etc complete.				
A	Cost of Spares Charges				
1	TC01376 / 40 SEAL KIT ASSLY	1 No.			
2	TC01376 / 07 H E CUSH BUSH	1 No.			
В	Cost of Labour Charges				
1	Removing arm jack assly. from machine and refitting after repairs	1 Job			
2	Dismantling the cylinder assly , cleaning , replacing seal service kit with test & trial	1 Job			
	Total Rs.				
	Add GST				
	Grand Total Rs.				

\$

Deputy Engineer
Mech. Sub Division (L.T.P) Latur