

WORK DETAILS

Name of work : Repair & Reconditioning of RETURN PIPING(1),DELIVERY PIPING, SHORT ARM assly & SUCTION PIPING of Tata Hitachi Ex350-402.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning of RETURN PIPING(1),DELIVERY PIPING, SHORT ARM assly & SUCTION PIPING of Tata Hitachi Ex350-402 by way of supplying Spare parts & Labour Charges.					
A	Providing & fitting following spares as per OEM Specification					
1	TD02941	PIPE;RETURN	1	No.		
2	4355107	HOSE	1	No.		
3	TE03800	HOSE	1	No.		
4	4399783	Hose	1	No.		
5	4387448	PLATE;THRUST	2	No.		
6	14280598209	HOSE CLAMP	2	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		4	Job		
GST 18%						
Total Rs						



Deputy Engineer

Mechanical Subdivision, Latur