

Name of Work : Repair to recoil unit and idler group of JCB JS 80 No. 109485

Sr.No	Description of Job	Qty.
1	Repairs to recoil unit of JCB JS 80 No. 109485 by removing the track chain assly from machine, cheaking and removing wornoutparts, provinding and fitting new spars as per OEM specification	
1	331/20045 - Yoke	1 No
2	331/20048 - Bracket	2 No
3	998/10443 - Kit Seal	1 No
4	904/20188 - Seal	1 No
5	904/20190 - Seal/wiper seal	1 No
6	904/20189 - Seal	2 No
7	826/10579 - Pin tention	2 No
8	25/964902 - Solenoid coil	1 No
B	Cost of labour charges	
1	Disemntaling rack chain by removing master pin/ master link bolts	1 Job
2	Reassembling of track chain and fitting of master pin by hydraulic press	1 Job



Deputy Engineer
Mechanical Sub division No. 2
Osmanabad