

ENQUIRY

Name of Work : **Repair & reconditioning of R.H Side Boom Cylinder Assembly
of JCB JS 140 Excavator No. 2439386**

Sr. No .	Description		Qty	Estimated Rates		Remark
				Rate	Amount	
1	2		3	4	5	6
	Repair & reconditioning of R.H Side Boom Cylinder Assembly of JCB JS 140 Excavator No. 2439386 by Removing Arm Cylinder Assly from machine ,dismantaling assly , eye end rebuilding to std size & Replacing seal kit , bushing with new parts as per OEM specifications etc complete.					
A	Cost of Spares Charges					
1	335 / B 6905	SEAL KIT	1 Kit			
2	550 / 41153	NUT PISTON ROD	1 No			
3	550 / 43349	BUSH CUSHIONING H.E	1 No			
4	550 / 43351	BUSH	1 No			
5	550 / 43353	BUSH	1 No			
6	335 / B 6904	PIPE S/A	1 No			
7	KNJ 1920	HOSE	2 No			
B	Cost of Labour Charges					
1	Removing R.H Side Boom Cylinder Assly from machine & refitting after repair		1 Job			
2	Dismantling the cylinder assly , cleaning , replacing seal service kit with test & trial		1 Job			
3	Cylinder barrel end bushing replacement		1 Job			
4	Removing & refitting high pressure hose assembly		2 Job			
	Total Rs.					
	Add GST					
	Grand Total Rs.					



Deputy Engineer
Mech. Sub Division (L.T.P) Latur