

ENQUIRY

Name of Work : **Repairs & reconditioning to Front spring & suspension assly , Exhaust manifold & Turbocharger assly of Tata Tipper MH20CU0204.**

Sr. No .	Description		Qty		Estimated Rates		Remark
					Rate	Amount	
1	2		3		4	5	6
	Repairs & reconditioning to Front spring & suspension assly , Exhaust manifold & Turbocharger assly of Tata Tipper MH20CU0204.						
A	Cost of Spares Charges						
1	206732100111	ASSY. FIRST LEAF WITH BUSH	1	No			
2	206732107132	SECOND LEAF	1	No			
3	206732107134	FOURTH LEAF	1	No			
4	252509145812	HOSE-BOTTOM-AT TC INLET	1	No			
5	252514510111	Turbocharger	1	No			
B	Cost of Labour Charges						
1	Front spring leaf assly. removing, dismantling, recambering and refitting / Assy.(equivalent to7.5 Ton Tata/Leyland)		1	Job			
2	Turbocharger dismantling for repairs and refitting after repairs(equivalent to Tata Prima LX4928)		1	Job			
	Total Rs.						
	Add GST						
	Grand Total Rs.						

Deputy Engineer
Mech. Sub Division (L.T.P) Latur