Name of work :Repairs to Arm Cylinder Assly & Providing filter for JCB JS-80 No.109482

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	4	5	6	77
1)	Repairs to Arm Cylinder Assly of JCB JS 80 Ezcavator No.109482 by replacing thr following damaged and warnout parts as per OEM specification & part no.given below.				
A	Cost of Material				
5	594/14027 - Kit and cap 60mm rod x 110mm cyl.End cap	1	No		
В	Cost of Labour Charges			227	
	Removing Boom jack assly from machine & refitting after repaire (H/08)	1	Job		
	Dismentling of Jack assly, cleaning, inspection & resplacement of seal with test and trial (H/09)	1	Job		
	Total	of (M	aterial ·	+ Labour) 1St Rs:	
2)	Providing filter for JBC JS80 No.109482 as per OEM specificat	tion & p	art no.	given below.	
A	Cost of Material	11,1			
1	550/41640 - Safty Element	1	No		
2	550/41639 - Primary Element	1	No		
3	32/925185 - Main Return Filter	1	No		
4	32/925164 - Element Filter	1	No		
5	32/925233 - Suction Strainer Element	1.	No		
B 2	Complete Servicing of machine at priodic interval of 250/500/1000 working Hours including applicabel changing of fuel filter engine oil filter filters of hydraulic transmission teering system etc(E67)	1	Job		
			Tota	l of (A+B) 2nd Rs:	
Total : GST 9 % GST 9 %					
	Grand to				
				Say Amount	

Deputy Engineer
Mechanical Subdivision No.2
Osmanabad