

## **ENQUIRY**

Name of Work : **Repair & reconditioning of Arm Cylinder Assembly of JCB JS 140 Excavator No. 2439386**

Sr. No .	Description		Qty	Estimated Rates		Remark
				Rate	Amount	
1	2		3	4	5	6
	Repair & reconditioning of Arm Cylinder Assembly of JCB JS 140 Excavator No. 2439386 by Removing Arm Cylinder Assly from machine ,dismantaling assly , eye end rebuilding to std size & Replacing seal kit , bushing with new parts as per OEM specifications etc complete.					
A	<b>Cost of Spares Charges</b>					
1	335 / B 6884	SEAL KIT	1 Kit			
2	332 / Y 8651	NUT PISTON ROD	1 No			
3	335 / B 6879	BUSH CUSHIONING	1 No			
4	335 / B 6881	BUSH CUSHIONING H.E	1 No			
5	550 / 43355	BUSH	2 No			
6	550 / 43375	PIPE S/A	1 No			
7	KNV0756	PIN	1 No			
8	KNV0539	SHIM	2 No			
9	6009 / 3724Z	BOLT	2 No			
10	173R016VZ	NUT	4 No			
11	627 / 10648	HOSE	1 No			
B	<b>Cost of Labour Charges</b>					
1	Removing Arm Cylinder Assly from machine & refitting after repair		1 Job			
2	Dismantling the cylinder assly , cleaning , replacing seal service kit with test & trial		1 Job			
3	Cylinder barrel end bushing replacement		1 Job			
4	Removing & refitting high pressure hose assembly		1 Job			
	<b>Total Rs.</b>					
	<b>Add GST</b>					
	<b>Grand Total Rs.</b>					



**Deputy Engineer**  
**Mech. Sub Division ( L.T.P ) Latur**