

## दर सुची

जा. क्र. याउविला/तां.शा/12/2021

दिनांक :- 03/03/2021

प्रति, \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Name of work : Repair & reconditioning of LH side track adjuster of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 52473**

\*\*\*\*\*

प्रिय महोदय,

विषयांकित दुरुस्ती कामासाठीची दर सुची नोंदणीकृत अभिकरणाकडून निविदा मोहरबंद लिफाफ्यात मागविण्यात येत आहे. दर सुची निविदा या कार्यालयात दिनांक 10/02/2021 रोजी १७.०० वाजेपर्यंत सादर करावे.

**शर्ती व अटी :-**

१. दिलेले दर सर्व टॅक्स व इतर खर्चासहीत राहिल.
२. कामे पूर्ण करण्याचा कालावधी ७ दिवस राहिल.
३. दुरुस्त करण्यात आलेले यंत्र / घटक ६ महिने अथवा ५०० तास (जे नंतर असले ते) विना तक्रार चालतील याची हमी देणे बंधनकारक राहिल.
४. देयकातून १० टक्के रक्कम सुरक्षा अनामत म्हणून कपात करण्यात येईल व हमी संपल्यानंतर अनामत रक्कम मागणी केल्यावर परत करण्यात येईल.
५. ना दुरुस्त यंत्र / घटक यांत्रिकी उप विभाग लातुर येथे पूर्ण निरीक्षणासाठी उपलब्ध आहेत.
६. अपूर्ण / अंशतः माहितीचे अगर उशिरा प्राप्त झालेले दर सुची विचारात घेण्यात येणार नाहीत.
७. निम्न स्वाक्षरीतांना कोणतेही दर सुची निविदा कोणतेही कारण न देता नाकारण्याचा अधिकार राहिल.
८. निकामी / निरूपयोगी सुटे भाग संबधिताना परत करून आपल्या बीजकात तसे प्रमाणीत करावे

आपला विश्वासू



उप अभियंता

यांत्रिकी उप विभाग लातुर

प्रत.कार्यकारी अभियंता यांत्रिकी विभाग, उस्मानाबाद यांना त्यांचे पत्रजा.कं यांविउ.ताशा.1/468 दिनांक 01.03.2021 अनुषंगाने माहितीस्तव सविनय सादर.  
प्रत सुचना फलक

Name of work : Repair & reconditioning of LH side track adjuster of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 52473

Part Details								
Sr. No.	Part Number		Description		Qty.		Rate	Amount
	Repair & reconditionig L.H. sides track adjuster of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 52473 by Dismantalling track chain by removing master pin ,Repairs to recoil cylinder by replacing l new parts as per OEM specifications & Reassembling of track chain & fitting of master pin by hyd. Press.							
A	cost of spares charges							
1	3098282	SPRING	1	No				
2	4360347	O RING	1	No				
3	4182361	RING WEAR	1	No				
4	4179303	PACKING O RING	1	No				
5	959499	RING RETAINING	1	No				
6	4449766	RING WEAR	1	No				
7	4413075	SEAL DUST	1	No				
8	4357539	NUT	1	No				
9	4255055	VALVE	1	No				
10	M340820	BOLT	4	No				
B	Cost of Labour Charges							
1	Dismantalling track chain by removing master pin/ master link bolts				1	job		
2	Repairs to recoil cylinder by replacing oil seal .Complete job				1	job		
3	Reassembling of track chain & fitting of master pin by hyd. Press.				1	job		



(Y.S.Biradar)  
Deputy Engineer  
Mechanical Subdivision, Latur