


Name of work : Repairs to Swing joint assly of Sany 140 No. 14381161

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
1	Repairs to swing joint assly of sany 140 No 14381161 by removing swing joint from machine. removng old and unservisable seal kit and Hyd.Hoses. Providing & fitting new seal kit & Hydraulic hoses as per OEM specification given below.				
A	Cost Of Material				
1	B230103005402 - Rubber hose 4SP20-DKOS-SFL90-1800Q/SY110	3	No		
2	B230103007774 - Rubber hose	1	No		
3	40270960 - Swing Joint repair kit	1	No		
B	Cost of Labour Charges				
1	G/12 - Centre (Swing) joint overhauling	1	Job		
2	H/06 - Removing & refitting high pressure hose assly.	3	Job		
				Total	
				SGST 9%	
				CGST 9%	
				Grand Total	
				Say Amount	

  
Deputy Engineer  
Mechanical Subdivision No.2  
Dharashiv