Work:- Repairs to 01 No of 0.6X0.6 mtr Sliding Type & 2 Nos of 0.45X0.45 mtr SlidingType R. R. Gate and painting of HR at Kasari M. I. Tank Dist.-Gadchiroli.

F	ABSTRACT				Amount
SN	Description	Qty	Unit	Rate	Amount
1	Repairs of Canal Gate of size 0.6X0.6 m by Dismantling of stem rod, Hoist, skin plate, Replacing bush, New stem rod 45 mm dia and 4 m, New stem Nut with ID 45 mm, hoist assembly with bearing, bearing housing Greasing of stem rod, etc. (As Per RA-1)	1	No	53330.00	53330.00
2	Repairs of Canal Gate of size 0.45X0.45 m by Dismantling of stem rod, Hoist, skin plate, Replacing bush, straightening, cleaning stem rod 40 mm dia and 4 m. New stem Nut with ID 40 mm, replacing bearing, Greasing of stem rod, etc. (As Per RA-2)	2	No	40516.42	81032.83
3	Providing and applying ANTICORROSIVE COAL TAR BLACK paint IS 290-1961 in two coats to repaired gate leafs of various sizes at Kasari MI Tank project project (as per RA-3)	7.26	m2	405.72	2945.5
4	Transportation charges: To and Fro Distance Between gadchiroli and Kasari M. I. Tank = 120 km (As Per	240	km	50.90	12216.9
	RA-4)		Tota	l amount :-	149525.3
	Total:-				
Add 1% Insurance Charges:- Total amount :- Add 18% GST Total amount :- say					149.5
					149674.8
					y 176616.0

(Amount in words: Rupees One Lakh Seventy Six Thousand Six Hundred Sixteen only)

Estimate Prepared by me

P.S.Thakare

Assistant Engineer Gr-II Lift Irrigation Mechanical Subdivision No.3 Chandrapur

Senctioned Estimate No. 52 Year 23-20t.

Amount Rs 176616 in Words one lake Seventy

Six Thousand and Six hundred

and Sixteen,

N.B. Aghshe
Deputy Engineer
Lift Irrigation Mechanical
Subdivision No.3 Chandrapur

Executive Engineer Mechanisal Lift Imigation Dri No. 2 Chandrapur