


## WORK DETAILS

**Name of work : Repair to LOADER PIPING, BACKHOE ASSY (LINK), BACKHOE ASSY (BUCKET) & BACKHOE ASSY (BOOM) of BEML BL9H-Loader No.10560.**

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to LOADER PIPING,BACKHOE ASSY (LINK),BACKHOE ASSY (BUCKET) & BACKHOE ASSY (BOOM) by way of supplying sapres as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	784PH02193	HOSE	2	No.		
2	CHH0400811	HOSE	2	No.		
3	CHH0401004	HOSE	1	No.		
4	CHH0400809	HOSE	2	No.		
5	474MD31067	TOOTH (CASTING	3	No.		
6	474BH02213	ARM LINK	1	No.		
7	474BH02376	PIN	1	No.		
8	474BH02295	PIN	1	No.		
B	LABOUR CHARGES					
1	Repairs to bucket by replacing the teeth for loader / No.		3	Job		
2	Removing bucket/arm/boom jack assly. from machine and refitting after repairs(Equivalent)		2			
3	Removing and refitting high pressure hose assembly		7			
					GST 18%	
					Total Rs	

  
**Deputy Engineer**  
**Mechanical Subdivision, Latur**