


WORK DETAILS

Name of work : Repairs to Hydraulic pump assly. of TATA Hitachi 120 H No.52806

Sr. No.	Part Details		Qty	Rate	Amount
	Part Number	Description			
	Repairs to Hydraulic pump assly. of TATA Hitachi 120 H No.52806 by way Dismenraling Hydraulic pump assly.and inspecting, Replacing damaged spares as mentioned below &assembling pump by using new spares as per OEM Specification & part number given below.				
A	Providing & fitting following spares as per OEM Specification				
1	2042059	Rotor	1	No.	
2	2044793	Plate valve	1	No.	
3	4355272	Baring needle	1	No.	
4	4463047	Seal Kit	1	No.	
B	LABOUR CHARGES				
1	Removing Hydraulic pump from mahine and Fitting after		1	Job	
2	Complete fuel line opening, cleaning, checking, brazing and refitting		1	Job	
3	Silencer/muffler repairing by removing, cleaning and refitting with welding work		1	Job	
					GST 18%
					Total Rs


Deputy Engineer
Mechanical Subdivision, Latur