

ABSTRACT

Name of Work: Repair of track link group assembly of TATA Hitachi ZX 220 no. 305


Sr.No.	Description	Qty.	Rate	Amount
1	Repair of track link group assembly of TATA Hitachi ZX 220 no. 305 by Replacing the required spares of the travel device	1		128633
2	Cost of labour charges	1		21324
			Total =	149957
			G.S.T. 18% =	26992.26
			Total	176949.26
			Say =	176949.00


(In Words:- Rs. . One lakh seventy six thousand nine hundred forty nine only).

CERTIFICATE

Certified that,

- 1- Repairs are essential to keep machine in good working condition.
- 2- Spares are not available in dept. stores.
- 3- Such type of repair jobs are not carried out in our work shop due to lac of facilities.
- 4- Rates are reasonable.
- 5- Certify that the above repairs work is to be carried out immediately as the Dozer is urgently required on Project Canal Earth Work.



Shri. B.V. Satpute,
Sect. Engr.


(Shri. C.T. Satpute)
Deputy Engineer,
Mechanical Sub Division No.3
Osmanabad

Sanctioned Estimate No.....the year. 2020-21

Estimate technically Sanctioned for Rs

Rs. In Word.. one Lakh seventy six Thousand Nine Hundred forty Nine only.



Executive Engineer
Mechanical Division
Osmanabad


Measurement sheet

Name of Work : **Repair of track link group assembly of TATA Hitachi ZX 220 no. 305**

Sr.No.	Description	Qty.	Rate	Amount
1	Dismantling track chain by removing master pin/set	1	1330	1330
2	Repair of track link group assembly of TATA Hitachi ZX 220 no. 305 by Replacing the following spares of the travel device			
2.1	TD03656/12 Track bolt	24	381	9144
2.2	TD03656/2 Track link LH	3	4945	14835
2.3	TD03656/5 Track pin regular	8	2041	16328
2.4	TD03656/7 Track bushing regular	6	2949	17694
2.5	TD03656/9 Dust seal	15	469	7035
2.6	TD03656/14 Track shoe	6	7299	43794
2.7	TD03656/1 Track link RH	3	4945	14835
2.8	TD03656/13 Track nut	24	207	4968
3	Removing and refitting new link bush, pin of track chain /set (inner and outer)	8	2326	18608
4	Reassembling of track chain and fitting of master pin by hydraulic press	1	1386	1386
			Total =	149957
			G.S.T.18%	26992.26
			Total =	176949.26
			Say=	176949

(In Words:- Rs. One lakh seventy six thousand nine hundred forty nine only).


Shri. B.V. Satpute,
Sect. Engr.


(Shri. C.T. Satpute)
Deputy Engineer,
Mechanical Sub Division No.3
Osmanabad