


Work Details

Name of work : Repairs & reconditioning to bucket jack assly.of L & T Ck72 No. 995

| Sr. No. | Part Details | | Qty / Unit | | Rate | Total |
|---------|----------------------------------------------------------------------------------------------------|------------|------------|------|------|-------|
| | Repairs & reconditioning to bucket jack assly.of L & T Ck72 No.995 | | | | | |
| A | Cost of Spares | | | | | |
| 1 | 300228631 | Crome Bush | 2 | Nos. | | |
| 2 | 302496395 | Seal Kit | 1 | Nos. | | |
| | Cost of Spares Rs : | | | | | |
| B | Cost of Labour | | | | | |
| 1 | Removing bucket/arm/boom jack assly. from machine and refitting after repairs. (H/08) | | 1 | Job | | |
| 2 | Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria. (H/09) | | 1 | Job | | |
| | Cost of Labour Rs : | | | | | |
| | Total of (Spares + Labour) Rs : | | | | | |
| | GST @ 18% Rs : | | | | | |
| | Grand Total Rs : | | | | | |


(S.S.Garad)

Deputy Engineer
Mechanical Subdivision No. 3,
Dharashiv