

Name of work : Repairs to Track Chain Assly R.II Side of Sany 140 Excavator No.14381211

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
1	Repairs to Track Chain Assly R.II Side of Sany 140 Excavator No.14381211 by removing old spares and providing and fitting following new spares as per OEM specification given below.				
A	Cost of Labour Charges				
1	Dismantling Track chain by removing master pin/no (UC/01)	1	Job		
2	Removing Grouser Shoe Bolts by gas cutting & refitting of Grouser Shoe (UC/14)	4	Job		
3	Removing & refitting new Link Bush,Pin of Track Chain/Set (Inner & outer (UC/13)	3	Job		
4	Reassembling of Track Chain & fitting of Master Pin y Hydraulic Press	1	No		
Total A					
B	Cost of Spare Parts				
1	11176813-Track Link/R	4	No		
2	11176814-Track Link/L	3	No		
1	60018963-Bolt	16	No		
2	60018959-Nut	16	No		
3	11176808-Bush	3	No		
4	11176807-Pin	3	No		
Total B					
Total A + B					
SGST 9%					
CGST 9%					
Grand Total					
Say Amount					

(B.V.Satpute)
Deputy Engineer
Mechanical Subdivision No. 02,
Dharashiv