



Name of Work : Repairs to Tata Hitachi 120 Excavator No.52474.

Sr.No	Description of Job	Qty.
A	Repairs to Bucket cylinder assly of Tata Hitachi Ex.120 No. 524744 by replacing damaged and worn out spares from machine and fitting new spare parts as per O.E.M. specification and equivalent part number given below	
	TC01377/37 – Seal kit	1 No.
	TC01377/4 – Piston rod nut	1 NO.
	4333699 – Hose	1 No
	TC01377/9 – Pipe S/A	1 No
B	Labour Charges	
	Removing Bucket Cylinder Assly from machine and refitting after repairs	01 Job
	Removing and refitting non hidden high pressure hoses and main piping	02 Job
	Dismelting cylinder assly cleaning, replacing seal service kit	01 Job



Deputy Engineer,  
Mechanical subdivision no. 2,  
Osmanabad,