

ENQUIRY

Name of Work : ***Repair & reconditiong of Hydraulic System (Control Valve to Front Piping) of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 51573***

Sr.No.	Description		Qty	Estimated Rates		Remark
				Rate	Amount	
1	2		3	4	5	6
	Repair & reconditiong of Hydraulic System (Control Valve to Front Piping) of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 51573 by Removing unservicable Hose assly , O Ring etc from machine ,& Replacing hose assly , O Ring etc with new parts as per OEM specifications etc complete.					
A	<i>Cost of Spares Charges</i>					
1	43328727	HOSE ASSLY	1 No			
2	4510167	'O " RING	1 No			
3	4455222	HOSE ASSLY	1 No			
4	Z971489	'O " RING	1 No			
5	4425161	HOSE ASSLY	1 No			
6	4510167	'O " RING	2 No			
B	<i>Cost of Labour Charges</i>					
1	Removing & refitting Non hidden high pressure hoses & Pipe Assly		4 Job			
	<i>Total Rs.</i>					
	<i>Add GST</i>					
	<i>Grand Total Rs.</i>					



Deputy Engineer
Mech. Sub Division (L.T.P) Latur