

Abstract


Name of Work:- Repairs & reconditioning Bucket cylinder assly of Tata Hitachi 120 H No. 52474


Sr. No.	Description	Qty	Rate	Amount
1	2			
A	Repairs & reconditioning Bucket cylinder assly of Tata Hitachi 120 H No. 52474			
1	Cost of Spares	1 Job	35628.00	35628
2	Cost of Labours charges	1 Job	6574.00	6574
			Total :	42212.00
			GST 18 %	7598.00
			Total	49810.00

Total in Words- Rs (Fourty Nine thousand eight hundred ten Only)

Certificates:-

- 1 Repairs are essential to keep the machine in good working condition
- 2 Such type of repairs are not done in dept al work shop due to lack of facilities
- 3 Spare are not available in dept.al store
- 4 Rates are resanable.
- 5 Rate of labour are taken from DSR 2019-20

  
B.V. Satpue  
Sectional Engineer

  
Deputy Engineer  
Mechanical Subdivision No.2  
Osmanabad


sanctioned Estimate No.....the year. 2020-21  
Estimate technically Sanctioned for Rs 49,810/-  
Rs. In Word.. Fourty..Nine..Thousand Eight Hundred Ten.


  
Executive Engineer  
Mechanical Division  
Osmanabad

## Measurement

Name of work :- Repairs & reconditioning Bucket cylinder assly of Tata Hitachi 120 H No. 52474

Sr. No.	Description	Qty	unit	Rate	Total Amount Rs
1	2	3	4	5	6
A	Repairs & reconditioning Bucket cylinder assly of Tata Hitachi 120 H No. 52474				
A1)	Removing Bucket cylinder assly from machine and refitting after repairs to machine	1	job	3598	3598.0
2	Removing and refitting non hidden High pressure hoses & main piping	2	job	636	1272.0
3	Dismantling cylinder assly cleaning replacing seal service kit	1	job	1704	1704.0
B	Providing & fitting following spares as per OEM specification & part NO. given below				
1	TC01377/37 seal kit	1	No	17523	17523
2	TC01377/4 criston rod nut	1	No	2374	2374
3	4333699 hose	1	No	11946	11946
4	Tc01377/9 pipse S/A	1	No	3795	3795
				Total	42212.00
				GST 18 %	7598
				Total	49810.00

  
B.V. Satpue  
Sectional Engineer

  
Deputy engineer,  
Mechanical Subdivision no. 2,  
Osmanabad