

Name of work :- Repair & Reconditioning to Arm jack ( Stick Jack ) Assly of TATA Hitachi 120 H No. 52474

Sr. No.	Part No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & Reconditioning to Arm jack ( Stick Jack ) Assly of TATA Hitachi 120 H No. 52474 by inspecting jack, dismantling from machine, cleaning & replacing unservicable parts as per OEM Specification of given below.					
<b>A</b>	<b>Cost of Spare</b>					
1	TC01376/40	Seal Kit	1	No.		
2	4352400	Bushing	1	No.		
3	TC01376/5	Piston Rod Nut	1	No.		
	<b>Total of Spares Rs :</b>					
<b>B</b>	<b>Cost of Labour</b>					
1	Removing & refitiing blade hoist/tilt/ripper jack assly. from machine. (H/07)		1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test &trial. (H/09)		1	Job		
3	Cylinder barrel end bushing replacemeng ( H/11)		1	Job		
	<b>Total of Labour Rs :</b>					
	<b>Total Spares+Labour Rs :</b>					
	<b>CGST 9 % Rs :</b>					
	<b>SGST 9 % Rs :</b>					
	<b>Grand Total Rs :</b>					
	<b>Round Off Rs :</b>					

  
**Deputy Engineer**  
 Mechanical Sub Division No.2,  
 Dharashiv