

ENQUIRY

Name of Work : ***Repair & reconditioning of Swing Drive unit (Plantery Gear) & Replacing of Hyd. Hose of BEML BE 200 Excavator No. 10076***

Sr. No .	Description		Qty	Estimated Rates		Remark
				Rate	Amount	
1	2		3	4	5	6
	Repair & reconditioning of Swing Drive unit (Plantery Gear) of BEML BE 200 Hydraulic Excavator No. 10076 by Dismantling Swing Drive Plantery Gear unit , cleaning removing unservicable Bearing , Seal , Race etc from machine & removing unservicable Hyd. Hose from machine .Replacing with new parts as per OEM specifications etc complete.					
A	<i>Cost of Spares Charges</i>					
1	781 HS 95016	TAPERED ROLLER BEARING.	1 No			
2	781 HS 94839	NILOS RING	1 No			
3	781 HS 95032	SEAL RING	1 No			
4	781 PH 91137	HOSE (ARM CYLINDER LINE)	1 No			
5	781 PH 61612	O RING	2 No			
6	781 PH 51674	SPLIT FLANFE	4 No			
B	<i>Cost of Labour Charges</i>					
1	Overhauling of swing motors by dismantling, cleaning and inspection of parts, reassembling etc.		1 Job			
2	Removing & refitting Non hidden high pressure hoses & Pipe Assly		1 Job			
	<i>Total Rs.</i>					
	<i>Add GST</i>					
	<i>Grand Total Rs.</i>					



Deputy Engineer
Mech. Sub Division (L.T.P) Latur