


Work Details

Name of work : Repairs & Reconditioning to Jack Assembly of TATA Hitachi Zx 220 No. 305

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	8
	Repairs & Reconditioning to Jack Assembly of TATA Hitachi Zx 220 No. 305 by removing dismantling & refitting jack assembly				
A	Providing & refitting following spares parts as per OEM Specification given below.				
1	TE 07941 - Seal Kit	1	No		
2	TC 007394/10 Bush	1	No		
3	TC 01398/14 - Pipes	1	No		
	Cost of Spare Rs :				
B	Cost of Labour				
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs.	1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria.	1	Job		
3	Eye end rebuilding & making to STD size.	1	Job		
	Cost of Labour Rs :				
	Total Spares + Labour Rs :				
	CGST @ 9% Rs :				
	SGST @ 9% Rs :				
	Total Rs :				


 Deputy Engineer
 Mechanical Subdivision No. 3,
 Dharashiv