

Name of work : Repairs to track chain assly (LH Side) of Sany 140 No. 14381211

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
1	Repairs to track chain assly (LH Side) of Sany 140 No. 14381211 by removing old spares and providing and fitting following new spares as per OEM specification given below.				
<b>A</b>	<b>Cost of Labour Charges</b>				
1	Dismaintaing Track chain by removing master pin /no. (VC/01)	1	Job		
2	Removing grouser shoe bolts by gas cultting & refitting of grouser shoe with new shoe bolts / shoe (VC/14)	4	Job		
3	Removing & refitting new link bush, pin of track chain / set (inner & outer)	4	Job		
4	Reassembling of track chain & fitting of master pin by Hydraulic press	1	Job		
	<b>Total A</b>				
<b>B</b>	<b>Cost of Spare parts</b>				
1	11176813 Track link / R	4	No		
2	11176814 Track link / L	3	No		
3	60018963 Nut	16	No		
2	60018959 Nut	16	No		
3	11176808 Bush	3	No		
4	11176807 Pin	3	No		
	<b>Total B</b>				
	<b>Total A + B</b>				
	<b>SGST 9%</b>				
	<b>CGST 9%</b>				
	<b>Grand Total</b>				
	<b>Say Amount</b>				



Deputy Engineer  
Mechanical Subdivision No.2  
Osmanabad