

## MEASUREMENT

**Name of work : Repair & Reconditioning to Cooling System and  
Seat Cushioning of BEML BE 200 Hydraulic  
Excavator No. 10076**

Sr. No.	Part Details		QTY	Rate	Amount
	Part Number	Description			
	Repair & Reconditioning to Cooling System of BEML BE 200 Hydraulic Excavator No. 10076 removing Radiator Assly and Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting . Repairing the water pump by replacing water pump kit and unservicable Spares by Providing & fitting following spares as per OEM Specification . And Cushioning of Operator seats & back rests cushioning with coir foam 4" with U foam 2" with best quality rexine cover .				
a	Cost of Spares Charges				
1	11 Z 9900329	Water Pump Repair Kit	1 Kit		
2	10 Z 6180236	Hose	1 No		
3	CCC01 - 05012	Clip	2 No		
4	781 EC 61011	Hose	1 No		
5	781 EC 61028	Hose	1 No		
6	CCC01 - 00902	Clamp	2 No		
7	CCC01 - 07020	Clip	2 No		
	Sub Total of a Rs.				
b	Cost of Labour Charges				
1	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting		1 Job		
2	Repairing the water pump by replacing water pump kit		1 Job		
3	Complete seats & back rests cushioning with coir foam 4" with U foam 2" with best quality rexine cover (Job With Material)		1 Job		
	Sub Total of b Rs.				
	Total ( a+b ) Rs.				
	Add GST @				
	<b>Grand Total</b>				



Deputy Engineer  
Mechanical Subdivision( LTP ) Latur