WORK DETAILS

Name of work: Repairs & reconditioning to BELT & PULLEY assly, Door assly., BRAKE CIRCUIT assly. & Front Suspension Assly.etc. to Mahindra Traco Transporter 35Ton-MH25U1379.

| Sr. No. | Part Details | | | \. | Rate | Amount | |
|------------|--|--|---|----------|--------------|------------|--|
| | Part Number | Description | | ()ty | Natu | 7 Illiount | |
| | Repairs & reconditioning CIRCUIT assly. & Front 35Ton-MH25U1379. | g to BELT & PULLEY assly, Door assly., BRAKE Suspension Assly.etc. to Mahindra Traco Transporter | | | | | |
| Α | Providing & fitting following spares as per OEM Specification | | | | | | |
| 1 | 0306GAV00010N | V BELT | 1 | No. | | | |
| 2 | 0306JAV00100N | ASSY TENSIONER PULLEY | 1 | No. | | | |
| 3 | 7311AAP00012N | FUEL TANK LOCK CAP-MINDA VALEO | 1 | No. | | | |
| 4 | 7708AAU00290N | PALM COUPLING(CONTROL LINE-YELLOW | 1 | No. | | | |
| 5 | 6111DAA00270N | ASSY OUTER DOOR HANDLE LH AND KEYSET-LH | 1 | No. | * E. | | |
| 6 | 6111DAA00280N | ASSY OUTER DOOR HANDLE RH AND KEYSET-RH | 1 | No. | - 1 - 1 2 | | |
| 7 | 7401AAP00200N | ASSY FIRST LEAF WITH BUSH (OP 2) | 2 | No. | | | |
| 8 | 7401AAP00220N | SECOND LEAF (OP 2) | 1 | No. | | | |
| 9 | 7401AAP00230N | THIRD LEAF (OP 2) | 2 | No. | | | |
| 10 | 7401AAP00240N | FOURTH LEAF (OP 2) | 1 | No. | | | |
| 11 | 7401AAP00260N | FIFTH LEAF (OP 2) | 2 | No. | 1.1 | , | |
| 12 | 7401AAP00280N | SEVENTH LEAF (OP 2) | 2 | No. | | | |
| 13 | 7401AAP00140N | SPRING CLAMP MIDDLE | 2 | No. | ·h. | | |
| В | LABOUR CHARGES | | | | Ŋ. | 1 | |
| 1 | Front spring leaf assly. recambering and refitting | | 1 | Job | | | |
| | | | | GST 18% | | | |
| | 90. | | | Total Rs | | | |

Deputy Engineer Mechanical Subdivision, Latur