

ABSTRACT


Name of Work :- Repairs & Reconditioning to final drive assly(RH side) of L&T CK 72 No.997


Sr. No.	Description	Qty	Rate	Amount
1	2			
A	Repairs & Reconditioning to final drive assly(RH side) of L&T CK 72 No.997			
1	Cost of Spares	1 Job	39440	39440
1	Cost of Machinning and Labour Charges	1 Job	2245	2245
			Total :	41685.00
			GST 18 %	7503.00
			Total	49188.00

Total in Words- (Rs.Fourty nine thousand one hundred & eighty eight Rupees Only)

Certificates:-

- Repairs are essential to keep the machine in good working condition.
- Spare are not available in departmental store.
- Rates are reasonable.
- Such type of repair job are not carried out in departmental workshop due to lack of facility.
- Rates of Spares are taken by reducing 12.5% from price list & Labour, Machining Charges are taken by reducing 14.5% from DSR rates and then added 18% of GST


B.V. Satpue
Sectional Engineer


Deputy Engineer
Mechanical Subdivision No.3
Osmanabad

Sanctioned Estimate No.....the year. 2020-21

Estimate technically Sanctioned for Rs


Rs. In Word.. Forty.....line. Thousand one Hundred
Eighty Eight only.



Executive Engineer
Mechanical Division
Osmanabad

MEASUREMENT SHEET

Name of Work :- Repairs & reconditioning to final drive assly (RH side) of L&T CK 72 No.997

Sr.No.	Description	Qty	Rate	Total Amount
1	Repairs & reconditioning to final drive assly (RH side) of L&T CK 72 No.997			
A	Dismantling the Track chain by removing master pin/master link bolts UC/07/01	01 Job	1116	1116
B	Replacing the following Parts & providing and fitting new spare parts as per OEM specification given below.			
1	203-460-63T Bearing	1 No	5350	5350
2	203-460-60L Bellow seal	1 No	17750	17750
3	201-398-07U Bearing	1 No	16340	16340
C	Reassembling of Track chain & fitting of master pin by Hyd press	1 job	1129	1129
			Total	41685
			GST 18 %	7503
			Total	49188


B.V. Satpute
 Sectional Engineer


Deputy Engineer
 Mechanical Subdivision No.3
 Osmanabad