## **ABSTRACT**

Name of work: Repairs to Inspection Vehicle TATA Sumo No.MH15AA165

gate of tht bank

ory. Pleas

		Qty	Rate	Amount &
Sr.No.	Repairs to Fuel System, Air cleaner assly and Radiator assly of TATA Sumo No.MH15AA 165 by removing the assly from vehicle dismantling, checking and replacing old unserviceable spares by new one as per OEM specification. Charges include cost of material and Labour charges with GST.	01 Job	43381/-	43981.00
Add CGST @9%				3904.29
Add SGST @9%				3904.29
Totak				51189.58
Say Rs.				51190

**Rs.Fifty One Thousand One Hundred Ninety Only** 

Sectional Engineer

**Gate Erection Sub Divisic** Kedgaon

R. No. / 42 /TS -1 of 2020 ~ 21

Technically sanctioned for Rs..42-538 /