ENQUIRY

Name of Work:

Repair & reconditiong of Hydraulic System (Pump Assly to Control Valve & Drain Piping) of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 51573

Sr.					Estimated Rates		
No .]	Description			Rate	Amount	Remark
1		2		Oty 3	4	5	
1	_)	4	3	6
	Repair & reconditiong of Hydraulic System (
	Pump Assly to Control Valve & Drain Piping)						
	of Tata Hitachi Zaxis 120 Hydraulic Excavator						
	No. 51573 by Removing unservicable Hose assly, O Ring etc from machine, & Replacing						
	hose assly, O Ring etc with new parts as per						
	OEM specifications etc complete.						
	OEM specifications	etc complete.					
A	Cost of Spares Charges						
1	4455403	HOSE ASSLY	1	No			
2	4422976	HOSE ASSLY	1	No			
3	Z971489	'O " RING	4	No			
4	J781035	BOLT;SOCKET;M10	16	No			
5	4506459	FLANGE;SPLIT	4	No			
6	4460593	HOSE ASSLY	1	No			
7	4332943	HOSE ASSLY	1	No			
В	Cost of Labour Charges						
1	Removing & refitting Non hidden high pressure						
	hoses & Pipe Assly		4	Job			
	Total Rs.						
	Add GST						
	Grand Total Rs.						

*

Deputy Engineer
Mech. Sub Division (L.T.P) Latur