


Name of work :Repairs and Reconditining Track motor assly LH.side of JCB JS-80 No.109485

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	4	5	6	7
1	Repairs and Reconditining Track motor assly LH.side of JCB JS-80 No.109485 by Providing and fitting Hydraulic Hoses as per OEM Specification and part no given below				
A	Cost of Material Charges				
1	20-950757 seal kit	1	No		
2	20-950735 bearing	1	No		
B	Cost of Labour Charges				
1	Labour Charges for opening,cleaning replacing spare parts overhauling of track motor assly LH side(A/10)	1	Job		
2	Dismantling Track chain by removing master pin/No UC/01	1	Job		
3	Reassembling of track chain & fitting of master pin by hydraulic press UC/15	1	Job		
Total :					
GST 9 %					
GST 9 %					
Grand total					
Say Amount					


 Deputy Engineer
 Mechanical Subdivision No.2
 Osmanabad