Name of Work:- Repairs to Idler assly (LII) of Tata Hitachi 120 H Excavator No. 52474

-					
Sr. No	Description	Qty	Rate	Amount.	St
	Repairs to Idler assly (LH) of Tata Hitachi 120 H Exc		1		
	Compete Job with				
A)	Cost of Spare Parts (Including GST)	1 Job	45475	45475	101.15
B)	Cost of Labour Charges (Including GST)	1 Job	2722	2722	4417
_		48197	4680		

Total Amount - Rs. Forty eight thousand one hundred ninety seven only eigut

Certified that,

CERTIFICATE

four

- 1. Repairs are essential to keep machine in good working condition.
- 2. Spares are not available in dept. stores.
- 3. Such type of repair jobs are not carried out in our work shop due to lack of facilities.

Sec.Engineer

Deputy Engineer Mechanical sub division No.2 Osmanabad

panctioned Estimate No......the year. 20-21 Rs. In Word forty size Mouscine eight hypopeed and ninetal four only

Drecutive Engineer Mechanical Division **Samanabad**

Measurement Sheet

_{20 of work:} Repairs to front Idler assly (LH) of Tata hitachi Ex.120H No. 52474

57 TO 18 5 TO	Description	Qty	Unit	Rate	GST	Total Rate	Amount
Sr. No.	2	3	4	5	6	7	8
1 A	Repairs to front Idler assly (LH) by Providing and fitting following spares by new one for replacement of damaged items of Tata hitachi 120H Excavator No. 52474			1713 2 2			
1	Axle shaft 3035618	1	No	10904	1963	12867	(12867) 12
2	O Ring A810060	2	No	66(65)	12	(77)	153 14
3	Bushing TD00673	2	No	1168	210	1378)	2756 25
4	Seal group 4153468	2	No	7417317	1317	(8634)	17268
5	Bearing 1020173	2	No	5267	948	6215	12430
						Total (A)	45475
В	Cost of labour charges						44172=
1	Dismantling Track chain by removing master pin/No. UC/01	1	Job	1116	201	1317	1317
2	Removing & refitting of idler assembly UC/08	I	Job	1191	214	1405	1405
				- · · · · ·		Total (B)	2722
			V			Total	48197 4

(Forty eight thousand one hundred ninety seven only)

B.V.Satpute

(Section Engineer)

four

Deputy Engineer,
Mechanical Subdivision No.2,
Osmanabad.