

Schedule 'B'

me of work- Repairs to 10H.P. Capacity Mody make low head High Discharge electric Submersible pumps G554T installed at Right Bank
Inspection Gallery at Bhatsa Dam.

Qty	Description					Rates		Unit Per.	Amount				
						In Figure	In Words						
1	Repairs to 10.0 H.P. Mody make DewateringSubmerssible Pump by way of removing from Left Bank Inspection Gallery , transporting to Work shop ,attending repairs,retransporting to site and Erection with fitting New Flexible Hose / Nipples/Clips/ Cable etc. complete					720176.00	Seven Lakh Twenty thousand One Hundred Seventy Six Only.	Job	720176				
	Sr No	Particulars	Qty	Unit	Rate (Rs.)					Amount (Rs.)			
	A	Cost of Overhauling of 10 H.P Including of OEM M/s.Mody Pumps Spares parts	1	Job	119542.00					119542.00			
	B	Cost of Miscellaneous Material											
		(1) Dutron Kanaflex Flexible Hose 4"	114	Mtrs.	2885					328890			
		(2) HDPE Nipple 4"	10	Nos.	1700					17000			
		(3) HDPE Clip 4"	20	Nos.	200					4000			
		(4) Nut,Bolt & Washiers	8	Kgs.	93					744			
	Total B									350634.00			
	C	Cost of Labour											
		Labour Chatrges for removing Pump from Right Bank Inspection Gallery , transporting to Wor:k shop ,attending repairs,retransporting to site and Erection with fitting New Flexible Hose / Nipples/Clips/ Cable etc. complete	1	Job	250000.00					250000.00			
	Total A + B + C									720176.00			
Grand Total Rs.									720176.00				
Total Twenty thousand One Hundred Seventy Six Only.													

In words: Rs. Seven Lakh Twenty thousand One Hundred Seventy Six Only.

Deputy Engineer
Mechanical Sub Division
Turbhe Navi Mumbai

Sr. Divisional Accounts Officer
Mechanical Stores & Development Division
Kalwa, Thane

Executive Engineer
Mechanical Stores & Development Division
Kalwa, Thane