

ENQUIRY

Name of work : Repair & reconditioning of Hydraulic System (Bucket Cylinder line & Track Frame Line) of BEML BE 200 Excavator No. 10076

Sr. No.	Description		Qty		Rate	Amount	Remarks
	Repair & reconditioning of Hydraulic System (Control Valve to Work Attachment & Boom Cylinder Line) of BEML BE 200 Hydraulic Excavator No. 10076 by Removing unservicable Piping , Hoses , O Ring etc from machine ,& Replacing Piping , hoses , O Ring etc with new parts as per OEM specifications etc complete.						
A	Cost of Spares Charges						
	BUCKET CYLINDER LINE						
1	781 PH 91145	HOSE ASSLY	2	No			
2	781 PH 91153	HOSE ASSLY	2	No			
3	781 PH 61604	O " RING	4	No			
4	781 PH 02458	PIPING ASSLY	1	No			
	TRACK FRAME PIPING						
5	781PH91097	HOSE ASSLY	4	No			
6	781 PH 61604	O " RING	8	No			
7	CFB27 11035	BOLT	8	No			
B	Cost of Labour Charges						
1	Removing & refitting Non hidden high pressure hoses & Pipe Assly		9	Job			
	Total Rs.						
	Add GST						
	Grand Total Rs.						



Deputy Engineer
Mech. Sub Division (L.T.P)
Latur