## **WORK DETAILS**

Name of work: Repair to Arm Short Assly, Cylinder Boom (L.H) Assly. & Main Piping Of Tata Hitachi Zx120-52473

Sr. No.	Part Number	Description	Q	ty	Rate	Amount
R	anainto Arm Sho		Qty		Kate	Amount
fc	Repair to Arm Short Assly, Cylinder Boom (L.H) Assly. & Main Piping Of Tata Hitachi Zx120-52473 by way of supplying following spare parts as per OEM Specification & part number given below.			,,,		
A Pi	Providing & fitting following spares as per OEM Specification			_		
1	4344898	BUSHING	1	No.		
2	4296276	HOSE	1	No.		
3	TC01374/39	SEAL KIT ASSY.	1	No.		
В	LABOUR CHARGES					
1 1 1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs		1	Job	•	
2 I	Removing and refitting high pressure hose assembly			Job		
GST 18% Total Rs						

**Deputy Engineer** 

Mechanical Subdivision, Latur