WORK DETAILS

Name of the work: Repair to Roofing and Ceiling in the Office of Deputy Engineer Mechanical Subdividon, Latur

It. No	Item of work	Quant ity	Rate	Unit	Amount
A	Roofing & Ceiling			2017	
	Providing and Fixing corrugated Galvanished iron sheets of			· ·	
1	0.63 mm thick (24BW.G.) for roofing without wind tiles including fastening with galvanised iron screws and bolts, lead and bitumen washers as pr drawing etc. Complete	36.71		sqm	
1	0.63 mm thick (24BW.G.) for roofing without wind tiles including fastening with galvanised iron screws and bolts,	36.71		sqm	
1	0.63 mm thick (24BW.G.) for roofing without wind tiles including fastening with galvanised iron screws and bolts, lead and bitumen washers as pr drawing etc. Complete	36.71	Add 12	sqm	
1	0.63 mm thick (24BW.G.) for roofing without wind tiles including fastening with galvanised iron screws and bolts, lead and bitumen washers as pr drawing etc. Complete	36.71	Add 12	27	+

Deputy Engineer
Mechanical Subdivision,
Latur