

## **MEASUREMENT**

**Name of work :      Repair & reconditioning of Cooling System , Fuel Line Assly   & Periodic servicing of  
Mahindra Bolero Pickup No. MH 25 P 5122**

Sr. No.	Description		Qty	Rate	Amount
	Repair & reconditioning of Cooling System , Fuel Line Assly & Periodic servicing of Mahindra Bolero Pickup No. MH 25 P 5122 by Removing Radiator Assly , Water Pump , from machine ,dismantaling Radiator chock up removing by cleaning all the tubes, & Replacing water pump assly , thremostat , etc . Also Complete fuel line opening, cleaning, checking, brazing and replacing damaged fuel line , fuel injector with new parts as per OEM specifications etc complete.				
A	<b>Cost of Spares Charges</b>				
1	0304EB0390N	WATER PUMP ASSY	1    No		
2	0304EB0190N	GASKET, WATER PUMP	1    No		
3	0304DB0730N	HOSE-THERMOSTAT HSG TO WATER PUMP	1    No		
4	0304EB0680N	THERMOSTAT HOUSING ASSY	1    No		
5	0305BAB02221N	INJECTOR LCCR	1    No		
6	0305BAM00260N	COMMON RAIL FUEL INJECTION	1    No		
7	0313AB1960N	AIR FILTER ASSEMBLY	1    No		
8	0313AC0280N	AIR ELEMENT	1    No		
9	9420000073	OIL FILTER CARTRIDGE (OPTIONAL	1    No		
10	1001CAA15521N	FUEL FILTER ASSY	1    No		
	Total of A				
	Add GST @ 18 %				
	Total of A Rs.				
B	<b>Cost of Labour Charges</b>				
1	E/46	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting	1    Job		
2	E/50	Replacing water pump assembly	1    Job		
3	E/41	Complete fuel line opening, cleaning, checking, brazing and refitting	1    Job		
4	E/43	Fuel tank opening cleaning, brazing & refitting	1    Job		
5	E/67	Complete servicing of machine at periodic interval including applicable changing of fuel filter, engine oil filter, filters of hydraulic, transmission,	1    Job		
	Total of B				
	Add GST @ 18 %				
	Total of B Rs.				
	Grand Total ( A + B )				
	Say Total Rs.				

P.P.Phaltane  
Sectional Engineer  
Mech. Sub Division ( L.T.P )  
Latur

Y.S.Biradar  
Deputy Engineer  
Mech. Sub Division ( L.T.P )  
Latur