

Abstract

Name of Work:- Repairs to Boom cyl assly of Tata Hittrachi 220Zaxis Excavator Sr. No. 306

| Sr. No | Description | Qty | Rate | Amount. |
|--------|--|-------|--------------|--------------|
| | Repairs to Boom cyl assly of Tata Hittrachi 220Zaxis Excavator Sr. No. 306 | | | |
| | Compete Job with | | | |
| A) | Cost of Spare Parts (Including GST) | 1 Job | 47573 | 47573 |
| B) | Cost of Labour Charges (Including GST) | 1 Job | 4728 | 4728 |
| | | | Total | 52301 |

Total Amount – Rs. Fifty ^{one} two thousand ^{seven} three hundred ^{five} one only

51705-00

CERTIFICATE

Certified that,

1. Repairs are essential to keep machine in good working condition.
2. Spares are not available in dept. stores.
3. Such type of repair jobs are not carried out in our work shop due to lack of facilities.
4. Rates are reasonable.

(B.V. Satpute)
Sec.Engineer

Deputy Engineer
Mechanical sub division No.2
Osmanabad

sanctioned Estimate No.....the year 2020-21
Estimate technically Sanctioned for Rs 51,705-00
Rs. In Word.. Fifty one thousand seven hundred
five only.

Executive Engineer
Mechanical Division
Osmanabad

Measurement Sheet


Name of work: Repairs to Tata Hitachi Ex.220 Excavator No. 306 as

| Sr. No. | Description | Qty | Unit | Rate | GST | Total Rate | Amount |
|---------|--|-----|------|-------|------|------------|-------------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| A | Providing & fitting following spares for repair to Tata Hitachi 220 Ex. 306 as | | | 16822 | 3028 | 19850 | 39700 |
| 1 | Seal kit Boom Cyl.(LH & RH) TEO7940 | 2 | No | 17074 | 3073 | 20147 | 40295 |
| 2 | End Bush TCO1397/8 | 2 | No | 1554 | 280 | 1834 | 3667 |
| 3 | End Bush TDOO716/07 | 2 | No | 1530 | 275 | 1805 | 3610 |
| | | | | | | Total (A) | 47573 46977 |
| B | Cost of labour charges | | | | | | |
| 1 | Dismantalling & refitting Hoist/Boom assy. after repair A/21 | 1 | Job | 4007 | 721 | 4728 | 4728 |
| | | | | | | Total (B) | 4728 |
| | | | | | | Total | 52301 |

(Fifty ^{one} two thousand ^{seven} three hundred & ^{five} one only)

51705=00


B.V. Satpute
(Section Engineer)


Deputy Engineer,
Mechanical Subdivision No.2,
Osmanabad.