

ABSTRACT

**Name of Work: - Repairs & reconditioning to Final Drive Assembly RH Side of L&T 72
Poclain No. 995**

Sr. No	Description	Qty	Rate	Amount	
				Rs.	Ps.
	Repairs & reconditioning to Final Drive Assembly RH Side of L&T 72 Poclain No. 995				
A	Cost of Spares	1 Job.	44726.00	44726=	00
B.	Cost of Labour Charges	1 Job.	2245.00	2245=	00
				46,971=	00
			CGST 9%	4,227=	39
			SGST 9%	4,227=	39
			Grand Total=	55,425=	00

Rs. Fifty Five Thousand Four Hundred Twenty Five Rupees Only

*Volume
B-2245
Interior*

Isaiah
Deputy Engineer
Mechanical Sub-Divn. No. 3
Osmanabad

Sanctioned Estimate No.....the year. 2020-21
Estimate technically Sanctioned for Rs 55,425/-
Rs. In Word.. Fifty Five Thousand Four Hundred
Twenty Five.

[Signature]
Executive Engineer
Mechanical Division
Osmanabad

MEASUREMENT SHEET


**Name Of Works :- Repairs & reconditioning to Final Drive Assembly RH Side of L&T 72 Poclain
No. 995**


Sr. No	Description	Qty	Rate	Amount
A	Repairs & reconditioning to Final Drive Assembly RH Side of L&T 72 Poclain No. 995			
1.	Dismantling Track Chain by Removing Master Pin / Bolts	1Job.	1116.00	1116.00 ✓
B	Providing & Fitting New Spare Parts as per OEM Specification & Equivalent Given Below			
1	201-398-06T – Bearing	1No	6224.00	6224.00 ✓
2	203-460-632 – Bellow Seal	1No.	19973.00	19973.00 ✓
3	006-304-12 F – O' Ring	1No.	50.00	50.00 ✓
4	201-398-07 U – Bearing	1No.	18479.00	18479.00 ✓
C	Reassembling of Track Chain & Fitting of Mater Pin By Hyd. Press	1Job.	1129.00	1129.00 ✓
				46,971.00 ✓
			CGST 9%	4,227.39 ✓
			SGST 9%	4,227.39 ✓
			NET TOTAL =	55,425.00 ✓

(Rs. Fifty Five Thousand Four Hundred Twenty Five Rupees Only)

CERTIFICATE

- 1) Repairs are essential to keep machine in good working condition.
- 2) Spares are not available in dept. store
- 3) Such type of repair job are not carried out in dept. work shop due to luck & facilities.
- 4) Rates are reasonable.


B.V Satpute
Sectional Engineer


Deputy Engineer
Mechanical Sub Divn No.3
Osmanabad