

**ENQUIRY**

Name of Work : **Repairs & reconditioning to Front spring & suspension assly, Fuel injection pump assly, Air compressor assly ,Intercooler assly, Water pump assly of Tata Tipper MH25U1482**

Sr. No .	Description		Qty		Estimated Rates		Remark
					Rate	Amount	
1	2		3		4	5	6
	Repairs & reconditioning to Front spring & suspension assly, Fuel injection pump assly, Air compressor assly ,Intercooler assly, Water pump assly of Tata Tipper MH25U1482						
A	<b>Cost of Spares Charges</b>						
1	206732100111	ASSY. FIRST LEAF WITH BUSH	1	No			
2	206732107132	SECOND LEAF	1	No			
3	206732107134	FOURTH LEAF	1	No			
4	206732107136	SIXTH LEAF	1	No			
5	252507140164	KIT H.P.LINES-ROTARY PUMP	1	No			
6	252509145811	HOSE-TOP-AT AIR FILTER INLET	1	No			
7	252513100126	CYLINDER HEAD ASSY	1	No			
8	252513103707	CYL SLEEVE A/C STD 94D	1	No			
9	252514603820	ALUMINIUM PIPE-TC TO IC	1	No			
10	252514603821	AL PIPE-INTERCOOLER TO ENGINE	1	No			
11	252520156306	V BELT COGGED 1325 MM LONG	2	No			
12	252520140116	ASSY FAN	1	No			
B	<b>Cost of Labour Charges</b>						
1	Front spring leaf assly. removing, dismantling, recambering and refitting / Assy.(equivalent to 7.5 Ton Tata/Leyland)		1	Job			
2	Removing & refitting high pressure hose assembly (Equivalent to Back-Hoe Loaders:)		1	Job			
3	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting.(Equivalent to 7.5 Ton Tata/Leyland)		1	Job			
	<b>Total Rs.</b>						
	<b>Add GST</b>						
	<b>Grand Total Rs.</b>						

Deputy Engineer  
Mech. Sub Division ( L.T.P ) Latur