Name of work: Repairs to Hydraulic System (Hoses & Pipes) of TATA Hitachi Ex 200 No. 8680

Sr. No.	Description		Quantity / Unit		Rate	Total
	Repairs to Hydraulic System of TATA Hitachi Ex 200 No. 8680 by removing old leakedge pipes & Hoses & providing & fitting following spares as per OEM Specification given below.				મર્જુ લક્ષ	5
A	Cost of Spares charges					
1	TD02120	Pipe	1	No	14	
2	TD02121	Pipe	1	No		
3	TD02122	Pipe	1	No		
4	TD02123	Pipe	1	No		
5	4196256	Hose	2	Nos		
					tal of Spares Rs.	
В	Labour Chagges				· ·· · · · .	
1	Removing & refitting high pressure hose assly. (H/06)		6	Jo		
2	Fuel tank opening cleaning, bra		1	Jo		
	Total of Labour Rs :					
	Total (Spares + Labour) Rs:					
	CGST 9%					
	SGST 9%					
	Grand Total Rs :					
	Round Off Rs:					

Deputy Engineer Mechanical Subdiv.No.2, Dharashiv

2 ن

4 U