

WORK DETAILS

Name of work : Repair to Main (1,4&5), Pilot (4) Piping of Tata Hitachi Zx120-52473.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Main (1,4&5), Pilot (4) Piping of Tata Hitachi Zx120-52473 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4203129	HOSE	1	No.		
2	4192047	HOSE	1	No.		
3	8080641	PIPE	1	No.		
4	8077223	PIPE	1	No.		
5	4285464	HOSE	2	No.		
6	4445676	HOSE	1	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		7	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur