

WORK DETAILS

Name of work : *Repair to Pilot (10 & 11), Return (2) & Drain Piping of Tata Hitachi Zx120-52473.*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Pilot (10 & 11), Return (1&2) & Drain Piping of Tata Hitachi Zx120-52473 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	7037063	PIPE	1	No.		
2	8064356	PIPE;RETURN	1	No.		
3	4444262	HOSE	1	No.		
4	4427838	HOSE	1	No.		
5	4427839	HOSE	1	No.		
6	4445716	HOSE	1	No.		
7	4426634	HOSE	1	No.		
8	4445799	HOSE	1	No.		
9	4442649	HOSE	1	No.		
10	A852133	ADAPTER	1	No.		
11	A852122	ADAPTER	1	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		9	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur