

दर सुची

जा. क्र. याउविला/तां.शा/ ११५२ /२०२१

दिनांक :- २२ / ०२ / २०२१

प्रति, _____

**Name of work : Repair & Reconditioning Boom Cylinder & Bucket Cylinder Assembly of Case
770 Backo Loader No. MH 24 AJ 7847**

प्रिय महोदय,

विषयांकित दुरुस्ती कामासाठीची दर सुची नोंदणीकृत अभिकरणाकडून निविदा मोहरबंद लिफाफ्यात मागविण्यात येत आहे. दर सुची निविदा या कार्यालयात दिनांक ०१ / ०३ / २०२१ रोजी १७.०० वाजेपर्यंत सादर करावे.

शर्ती व अटी :-

१. दिलेले दर सर्व टॅक्स व इतर खर्चासहीत राहिल.
२. कामे पूर्ण करण्याचा कालावधी ७ दिवस राहिल.
३. दुरुस्त करण्यात आलेले यंत्र / घटक ६ महिने अथवा ५०० तास (जे नंतर असले ते) विना तक्रार चालतील याची हमी देणे बंधनकारक राहिल.
४. देयकातून १० टक्के रक्कम सुरक्षा अनामत म्हणून कपात करण्यात येईल व हमी संपल्यानंतर अनामत रक्कम मागणी केल्यावर परत करण्यात येईल.
५. ना दुरुस्त यंत्र / घटक यांत्रिकी उप विभाग लातुर येथे पूर्ण निरीक्षणासाठी उपलब्ध आहेत.
६. अपूर्ण / अंशतः माहितीचे अगर उशिरा प्राप्त झालेले दर सुची विचारात घेण्यात येणार नाहीत.
७. निम्न स्वाक्षरीतांना कोणतेही दर सुची निविदा कोणतेही कारण न देता नाकारण्याचा अधिकार राहिल.
८. निकामी / निरुपयोगी सुटे भाग संबधिताना परत करून आपल्या बीजकात तसे प्रमाणीत करावे

आपला विश्वासू



उप अभियंता
यांत्रिकी उप विभाग लातुर

प्रत.कार्यकारी अभियंता यांत्रिकी विभाग, उस्मानाबाद यांना त्यांचे पत्रजा.क्रं यांविउ.ताशा.१/३२९
दिनांक १५.०२.२०२१ अनुषंगाने माहितीस्तव सविनय सादर.
प्रत सुचना फलक

**Name of work : Repair & Reconditioning Boom Cylinder & Bucket Cylinder
Assembly Case 770 Backo Loader No. MH 24 AJ 7847**

Part Details						
Sr. No.	Part Number	Description	Quantity		Rate	Amount
A	Repair & Reconditioning of Radiator Boom Cylinder Assembly Case 770 Backo Loader No. MH 24 AJ 7847 by removing Arm cylinder Assembly from machine, Dismantaling, cleaning, inspectioning. Removing Worn out seals & bushing and replacing unservicable spares with new spares as per OEM specification and fitting the Assembly to machine.					
1	SSP4216/47570425	SEAL KIT	1	No		
2	BSBMCMA065030/47628217	BI METAL BUSH	1	No		
3	CWM029130389/47570744	BUSH (CEC)	1	No		
4	CWM029130389/47570745	BUSH(ROD EYE)	1	No		
5	85826513	HOSE BOOM ROD END	1	No		
6	85826512	HOSE BOOM HEAD END	4	No		
B	Cost of Labour Charges					
1	Removing Bucket/arm/Boom Jack assly from machine and refitting after repairs.		1	Job		
2	Dismantaling Bucket/Arm/Boom Cylinder assly, cleaning, inspecting & replaceing of seal of seal with test and trial.		1	Job		
3	Cylinder Barrel End Bush Replacement		1	Job		
4	Removing and refitting high pressure hose assly		2	Job		
B	Repair & Reconditioning of Bucket Cylinder Assembly Case 770 Backo Loader No. MH 24 AJ 7847 by removing Bucket cylinder Assembly from machine, Dismantaling, cleaning, inspectioning. Removing Worn out seals & bushing and replacing unservicable spares with new spares as per OEM specification and fitting the Assembly to machine.					
1	SSP4218/47568736	SEAL KIT	1	No		
2	BWW040G12016	SNAP RING	1	No		
3	CWMO29090387/47568612	BUSH	2	No		
4	B03190509/85812180	HOUSE BUCKET CYL HEAD	1	No		
5	B03190509/85812181	HOUSE BUCKET CYL ROD	1	No		
B	Cost of Labour Charges					
1	Removing Bucket/arm/Boom Jack assly from machine and refitting after repairs.		1	Job		
2	Dismantaling Bucket/Arm/Boom Cylinder assly, cleaning, inspecting & replaceing of seal of seal with test and trial.		1	Job		
3	Cylinder Barrel End Bush Replacement		1	Job		
4	Removing and refitting high pressure hose assly		2	Job		


 (Y.S. Biradar)
 Deputy Engineer
 Mechanical Subdivision, Latur