## WORK DETAILS

Name of work: Repair & Reconditioning to Boom Bottom piping, Drain piping, suction piping & Delivery Piping of Tata Hitachi Ex350-402

Sr. No.	Part Details				Rate	Amount
	Part Number	Description	Qty			
	Repair & Reconditioning to Boom bottom piping, Drain piping, suction piping & Delivery Piping of Tata Hitachi Ex350-402 by way of supplying following Spare parts number given below.					
Α	Providing & fitting fol	lowing spares as per OEM Specification				
1	8069136	Pipe	1	No.		
2	4390646	Hose	1	No.		
3	4355570	Hose	1	No.		
4	14280598098	Clamp Hose	4	No.		
В	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly			Job	- 1 - 1 - 1 + 1	-
GST 18%						
Total Rs						

**Deputy Engineer** 

Mechanical Subdivision, Latur